



5831 123rd Drive NW Epping, ND 58843 701.264.3617





Meadowlark Blacktail Creek Williston, North Dakota		
Daily Report for March 22, 2015		
Weather Overview		
55° F High	27° F Low	Conditions: Sunny.
Activities Taken and Ongoing		
Planning	- Conducted surface water sampling in accordance with the Surface Water Sampling and Analysis Plan from March 6, 2015.	
	- Collected daily surface water BC-100- and SW-400-series locations as access and water conditions allowed.	
	- Continued tabulating and validating analytical data.	
	- Continued preparation of daily field sampling, SCAT and operations maps.	
	vegetation that had been deposited dur wildlife searches were also conducted. Blacktail Creek allowing for improved Observations and collection of lightly	ail Creek on the east side of Route 85, 144+00. The team also assisted in 00 to 138+00 to remove unattached oiled ring high water events. Meandering Water levels continued to recede in divisibility of shoreline conditions. oiled dead wildlife included the 2 dead fish (no oil) and 1 catfish (no oil). ents 50+00, 56+00, 58+00, 62+00,
Operations	- Continued daily water truck count at reviewing daily chloride results. Rem (ITs) only.	
	- Evaluated IT chloride data and turned on additional pumps because water level has decreased and concentrations have increased.	
	- Pumped water from Interceptor Trenches IT-001 through -005, IT-010 through -024 and IT-026 through -028. Did not pump from IT-025 today.	
	- Collected relevant GPS data to update Operational maps.	
	- Industrial Builders did not work today and will not be back onsite until Monday morning.	
	- Removed accessible hydrocarbon-affected vegetation to 2" above ground surface, leaving roots intact. Collected, bagged and placed material in roll-off containers for T&D.	
	- Clean Harbors will ramp up hydroca additional personnel starting tomorrov remove impacted vegetation and 5 we	
	- Clean Harbor strike team worked wit	th SCAT near SW-416 to remove



Meadowlark Midstream Company, LLC. 5831 123rd Drive NW Epping, ND 58843 701.264.3617

www.summitmidstream.com

	hydrocarbon impacts and bag them.	
	- Continued improving site roads, and graded and compacted Njos road today to remove ruts.	
	- Constructed oil shark panels in Blacktail Creek.	
	- Strata removed and resituated mats near IT-026 and the railroad bridge that were separating with heavy truck traffic.	
	- Strata removed and re-situated mats near IT-004 and IT-005 that were separating with heavy truck traffic.	
	- Strata installed stone at inside-corner sections of mats.	
	- Used pole nets to remove hydrocarbons collecting in containment boom.	
	- Used 70 bbl. vacuum truck to remove hydrocarbons in boom and accessible areas.	
	- Total volume of water pumped through $3/21 = 364,585$ Barrels.	
	- No Solids disposed on 3/21.	
Logistics	- Total staff onsite: 18 [PM – 1, HSE – 1, Ops – 8 (including waste, logistics runner and night coverage), Planning – 8 (0 Planning/Situation Lead, 1 Admin, 1 GIS, 2 Bio assessment/SCAT, 4 Field Assessment Staff)].	
<u>Upcoming Activities and Action Items</u>		
Upcoming Activities	- Improve site roads.	
	- Perform street sweeping on rig mats.	
	- Remove containment boom that is ineffective or damaged by high water and place in containment cell for decontamination.	
	- Remove accessible hydrocarbon-affected vegetation to 2" above ground surface, leaving roots intact. Collect, bag and place material in roll-off containers for T&D. We will have a full 6 teams working tomorrow.	
	- Continue collecting relevant GPS data to update Operational maps.	
	- Perform oversight on Industrial Builders installation of the sheet pile wall.	
	- Remove hydrocarbon-impacted containment boom in Blacktail Creek and replace with clean boom.	
	- Begin decontamination of oily boom in western containment cell.	
	- Continue maintenance of containment boom, oil shark barriers and ice barriers.	
	- Continue extraction and disposal of water from IT locations.	
	- Review SWPPP field conditions and make necessary changes based on site conditions.	
	- Install wattles around IT-016.	
	- Continue maintenance of Njos roads.	
	- Install reflective markers to prevent vehicle collisions with well stick-ups.	
İ	- Continue maintenance and troubleshooting on pumps, piping, valves and	



## Meadowlark Midstream Company, LLC.

5831 123rd Drive NW Epping, ND 58843 701.264.3617

www.summitmidstream.com

	hose.
	- Reconcile vacuum truck waste water tickets and daily totals.
	- Continue monitoring and recovering hydrocarbon based on SCAT recommendations, weather permitting.
	- Continue surface water, IT and groundwater sampling.
Action Items	- Submit work plans and investigation reports to NDDH as per schedule dated February 11, 2015.